


Pręty gwintowane DIN 976



L = 1m

L = 2m

L = 3m

d		sztuk w opakowaniu
M 2	+	20
M 2,5	+	20
M 3	+	100
M 4	+	100
M 5	+	100
M 6	+	100
M 8	+	50
M 10	+	25
M 12	+	20
M 14	+	10
M 16	+	10
M 18	+	10
M 20	+	5
M 22	+	5
M 24	+	5
M 27	+	5
M 30	+	5
M 33	+	5
M 36	+	5
M 39	+	5
M 42	+	5
M 45	+	5
M 48	+	5
M 52	+	1